



**PICKHEAD AXE HANGER KIT**

**P/N K5012**


**INSTALLATION INSTRUCTIONS**

For additional assistance call 888-514-0083 between 8AM-5PM EST or email: info@pactoolmounts.com


**CAUTION**

To avoid the risk of personal injury, property damage or product damage, please use the included fasteners for mounting.

- \* The bracket must be securely mounted to a stable surface and material.
- \* When mounting bracket to PAC TRAC aluminum products **P/N 7000**, **P/N 7020**, **P/N 7040**, **P/N 7050** with the included Trac Lok inserts **P/N 7016**, torque the screws to a maximum 15 in-lbs.
- \* PAC recommends regular and frequent inspections to be certain of proper operation and installation.



STANDARD MTG. HARDWARE		QTY
 P/N 2031	¼-20 x 1 S.S. S.S. Flat Head Screw	2
 P/N 2069LN	¼-20 Nylon Locking Nut	4
 P/N 3017	¼-20 x 1 S.S. S.S. Pan Head Screw	2



**FIGURE 1**  
(Thru Mounting Method)




## PICKHEAD AXE HANGER KIT - PT P/N K5012 INSTALLATION INSTRUCTIONS

For additional assistance call 888-514-0083 between 8AM-5PM EST or email: info@pactoolmounts.com

### CAUTION


To avoid the risk of personal injury, property damage or product damage, please use the included fasteners for mounting.

- \* The bracket must be securely mounted to a stable surface and material.
- \* When mounting bracket to PAC TRAC aluminum products **P/N 7000, P/N 7020, P/N 7040, P/N 7050** with the included Trac Lok inserts **P/N 7016**, torque the screws to a maximum 15 in-lbs.
- \* PAC recommends regular and frequent inspections to be certain of proper operation and installation.



PAC TRAC MTG. HARDWARE			QTY
PAC Fastener Packet P/N 7021 – <b>Axe Pocket</b>			
	P/N 2043	#10-24 x 1 S.S. Flat Head Screw	2
	P/N 2054	#10 S.S. Washer	2
	P/N 7016	TRAC LOK INSERT	2

PAC TRAC MTG. HARDWARE			QTY
	P/N 2046	#10-24 x 1 S.S. S.S. Pan Head Screw	2
	P/N 7016	TRAC LOK INSERT	2



**FIGURE 2**  
(PAC TRAC Mounting)